


Prasad V. Potluri Siddhartha Institute of Technology
(Autonomous)

Kanuru, Vijayawada – 520 007

(Affiliated to JNTUK, Accredited by NBA, ISO 9001:2015 Certified Institution)



Criteria - IV

4.4.2. Maintenance Registers

| Sno | Date | Department | Nature of complaint where | Who give complaint signature |
|----------|---------|--|--|----------------------------------|
| ① | 16/7/18 | ECE | Tube light not working Room no: 140. | R. MOHAN (B) D. BALAJI (B) |
| ② | 16/7/18 | Mechanical | Room no: 334, Fan not working | K. Venkata Rao - 104 |
| 3 | 16/7/18 | T.I Lab | Room no: 316, Computer Tablet-4 switch prob. J. Yogenand. | |
| 4 | 16/7/18 | ECE | class Rooms no: 353 & 371 Fan was not working (sound) - A. Raju | |
| | 18/7/18 | Library | nebulight - S. Nithikey J. Kalai | |
| 5 | 18/7/18 | EEE | 2-fans not working Room no: 434 (e-Yantra Lab) | R. SWATHI |
| | 19/7/18 | Mech | Room no 8229 - motor bearing sound (metallurgy lab) | N. Raghavarao. |
| | 19-7-18 | FED | 422c Research lab switch burned down contact: 418 room | G. SREDEVI 8125820455 |
| 20/7/18 | Mech | 3f and bearing sound basic work shop (Furnitory) | N. Raghavarao | work completed P. Mohan Rao Aun. |
| 20/7/18 | ECE | class Room no: 341A - Tubelight + Fan - Repair 341 - Tubelight Repair 371 - Tubelight + Fan Repair 366 - Tubelight Repair | ARE work assigned | Aun, mohan |
| 24/07/18 | ECE | Room no: 267 (CS lab) Fan not working | P. Dineshwar (B) | work assigned |
| 27/7/18 | CSE | CS Room no: 210 (class room) Fan not working Room no: 904 (staff room) | J. Ravinder (Faculty Co-ordinator) P. Mohan Rao (Aun) | work completed P. Mohan Rao Aun |

| work completed | who attend | work completed | Remarks |
|----------------|------------------------------|----------------|---------|
| work completed | Nagender, mohan | | work |
| work completed | Arun, Nagender | | work |
| work completed | mohan, Nagender | | work |
| work completed | Arun, Nagender | | work |
| work completed | Nagender, Arun | | work |
| work completed | Arun Kumar, K. Nagender Babu | | work |
| work completed | Arun, mohan | | work |
| work attended | Arun Kumar, Mohan Rao | | work |
| work completed | P. Mohan Rao Aun. | | work |
| work assigned | P. Mohan Rao, Nagender | | work |
| work completed | P. Mohan Rao Aun | | work |

Diplo. Electrical & Electronics Engg.
SRAO V. PUTLURI
SIDDHARTH INSTITUTE OF TECHNOLOGY
9277777777

| S.No | Date | Dept | complaint | Signature | S.No | Date | Dept | complaint | Signature |
|---------|--------------------------------|--|---|-------------------------|---------|-------|---|-------------------------------------|---|
| 1. | 19/2/2019 | MECH | Switch Replacement Room No: 124 Machine shop-I | K. Srinivas | | | | work done | P. mohit Rao |
| 2. | 8/3/19 | Civil Library Room 151. | Tube light problem | G. Venkatesh | 8/3/19 | Civil | | | K. Venkatesh 10 |
| 3. | 11/3/19 | Library | 2 Tube light. | A. Jave | | | | work completed. | P. mohit Rao, Nejambika |
| 4. | 18/3/19 | Communication Lab Room No: 261 | 10 KVA Servo Stabilizer continuous noise generator | A. Jave | | | | 20/3/19. Attends Shubhagiri problem | P. mohit Rao, Nejambika |
| 5. | 25/3/19 | EEE [Dept: library] [245] | fan problem | Q | | | | 28/3/19. work completed | P. mohit Rao. |
| 6. | 9/5/19 | EEE [Dept: library] [245] | fan problem | Q | | | | 3/6/19 Civil Room No 146 | 3 FAN Power Civil Run C. P. J. S. P. mohit Rao, Arun |
| 7. | 10/5/19 | ME Dept (Room: 231) 024 | Tube light holder (2012139474) phone | 4-LT 67 P. mohit Rao | | | | work completed | P. mohit Rao, P. mohit Rao |
| 8. | 3/6/19 | IT Dept (Rooms: - 304) | Fan not working | Q | | | | 3/6/19 work completed | Arun, motor Rao |
| 7/6/18 | IT Dept | 329/A 8303 Not working Fan | Ch. M. Koturavaru R | | 13/6/19 | EEE | Fan not working in class Room No: 365 work completed | A. S. S. P. mohit Rao | |
| 10/6/19 | FED | Fix one LED tube light in HOD-FED room. Room No: 418 | Q | | | | work completed | Arun, motor Rao | |
| 14/6/19 | EEE 3 Year S2 Room:- 263 | Fan is not working properly lagakshmi | | | 24/6/19 | EEE | Fan repair | K. Venkatesh, Arun | |

| No | Date | Dept | Complaint | Sign |
|-----|------------|------------------------|---|-----------|
| 1. | 21-6-2019 | 310, 316 | T.T Tubelight and fan not working | 97-98 |
| 2 | 21-6-2019 | Library | 270Bc 118 hrs 2 Fan | Abre |
| 3. | 26-6-2019 | 231 (ME) | Tube light failed | 08/2 |
| 4 | 26-6-2019 | 123 (ME) | Fan Repair | 05/2 |
| 5 | 26-6-2019 | ME - workshop | ^{Basic} fan Repair (Housewiring) | 8 |
| 6 | 27-6-2019 | ME CAM | Fan repair | PCWEN |
| 7 | 27-6-2019 | ME 123 certing fan | 123 ok 3 Fan Repair | 8 |
| 8 | 2-7-2019 | Library | 2 NOS three pimplus | |
| | 11 | V | 2 NOS Schots. | (Abre) |
| 9. | 3-7-2019 | ADLab(216) | 1 Fan & 1 Tubelight Problem | ED |
| 10. | 3-7-2019 | PLab(224) | Fan & 2 lights Problem | PP |
| 11. | 3-7-2019 | RDLab(211) | 2 Fan's & 2 led lights | (D) |
| 12. | 3-7-2019 | Room no 149, FEE | Room no 149. Tube light not working | (D) |
| 13. | 4-7-2019 | class Room no 365, 366 | 3 No's Tubelights not working | A. Raju |
| 14. | 5-7-2019 | class Room no 371 | Fan Bearings problem | A. Raju |
| 15. | 16-7-2019 | class Room no 341 | Gang Box Brake 3-F3 Braked | A. Raju |
| 16. | 17-7-2019 | Room no: 308 | 3 new tube lights need. | G. Tharap |
| 17. | 19-7-2019 | Room no 353 | All three tube lights are not working | G. Tharap |
| 18. | 19-7-2019 | class room | Fan Not working. | A. Raju |
| 19. | 20/7/19. | Room no 367 R, D, ECE | Room no 367 Ram & table not working | (D) |
| 20. | 21/7/19 | PD Guru Room no 7 | New. Tubelights By. pothu | |
| 21 | 23/7/19 | Room no 368 | Tubelight not working | (D) |
| | | 1424 | Tubelight and working change to be done. | (D) |
| 22 | 31-08-2019 | Room No: 334 | 3 plug pinsockets - 3 nos | Xyz |
| 23 | 14/08/2019 | Civil | Room No: 146 Fan Not working | B. ARI |
| 24 | 14/08/2019 | Room no 122 | Fan not working - 1 nos | 86 fans |
| | | | CAMLAB (mech DEPT) | 1 |

| Status. | Attended by | Signature |
|---------------------------|-------------------------|-----------|
| 310 completed | Arun, Nagendran' | |
| work completed | P. Mohan Rao, Arun | P.M. |
| work complete | P. Mohan Rao, Arun | P.M. |
| MBA (Room no) 460 (FAM-1) | G. Raju | G.R. |
| work completed | Arun, Mohan Rao | P.M. |
| work completed | Arun Mohan Rao | P.M. |
| work completed | P. Mohan Rao - Arun | P.M. |
| work completed | P. Mohan Rao - Arun | P.M. |
| work completed | P. Mohan Rao | P.M. |
| work completed | P. Mohan Rao, Mohan Rao | P.M. |
| work completed | Arun Mohan Rao | P.M. |
| work completed | Arun, Mohan Rao | P.M. |
| work completed | P. Mohan Rao | P.M. |
| work completed | Arun Mohan Rao | P.M. |
| work completed | Mohan Rao Arun Rao | P.M. |
| work completed | Mohan Rao Arun Rao | P.M. |
| work completed | Mohan Rao | P.M. |
| work completed | Mohan Rao Arun Rao | P.M. |
| work completed | Mohan Rao | P.M. |
| work completed | Arun, Mohan Rao | P.M. |

| SL No | Date | Branch | Complaint | Sign | |
|-------|------------|--------------|---|---------|-----------------|
| 1. | 30-1-2020 | R.M.308 | 1. 15 → wall Caving, 1 tube light. 1 fan repair 316-17 → wall caving. OK tube light 323-17 → 1 fan repair | get job | work completed. |
| 2. | 31-01-2020 | 208 | 2Tube lights not working English lab 208 | get job | work completed |
| 3. | 02-02-2020 | 244 | Socket, 3 switches (General) [Printer purpose] | get job | work completed |
| 4. | 02-02-2020 | 244 | Fan problem. | get job | work completed. |
| 5. | 02-02-2020 | Room No: 128 | 2 lights problems | get job | work completed |
| 6. | 06-02-2020 | Basic work | dead socket and power connection for cooler (Mechanical Dept.) | get job | work completed |
| 7. | 07-02-2020 | CF | class rooms 204/205, 2 lights 1 Fan problems Room No: 155 | get job | work completed |
| 8. | 12-02-2020 | CF | H.o.D Room 2 Lights problems Room No: 158 | B.V | Problem solved. |
| 9. | 29-02-2020 | CF | Room No: 158 Sub problem | B.V | work completed. |

85

3/12/2020 Room NO+156 c intl lob tube light not working

15/12/2020 Room NO 328 - Metrology Instrumentation Lab - fan - staff room - making sound [so much noise by fan] - Repair required.

15/12/2020 465. New Tube light issue

5/12/2020 129 Room 4 tube lights

6/12/21 R.No:316 - IT-Lab I - window A/c not power supply

7/12/21 Room NO: 256 - Faculty Room - Fan problem

30/12/2020 Room NO-225 Gent facilities tube light

2/1/2021 Room NO: 144. Fan Repair -

2/1/2021 Room NO: IT Lab Fan Repair -

2/1/2021 Room NO: 146 Fan Repair -

2/1/21 Library (6) Six Tube lights 1 Fan - A/c

9/12/21 C.V.I. 1 351 Room Faculty Room Tube light B.L.

16/12/21 Digital Library - one Computer Table - Power failure

IT Lab-I - R.no:316 - one Tube light - fail.

- Two pole MCB Trip - Table

16-2-21 AD Lab - 216 - Two Fan's Not working

23/12/21 Mechanical Dept - workshop fitting section -

Fan Repairing and tube lights - not working

25/12/21 Measuring Dept. Meas. Tools LAB - 2 R.no:122

SK Karimullah (Attender) - 2 not working

09/01/21 FE Department class Room NO.408 J.C. Naseer LCD projector fixing and power cable problem

work completed

shown,

M. Saad Khan

J. Parker.

work completed 31/12/2020

Ans.

work completed

Ans, mohan Rao.

work completed

Mohan Rao.

work completed

Alex, Mohan Rao.

work completed

Kavendra Singh

work completed

Ans. Mohan Rao.

work completed

Ans, Nagendrew.

fan work completed

Nagendra Babu.

work completed

Ans. T.P.

14.1.2021 108 18/01/21

Sights

| | | | |
|------------|-----------------|---------------------------|--|
| 19/4/21 | MBL | MDA Dept | Fan Not working - Varanasi |
| 18/6/21 | Digital library | Two fans not working - It | |
| 18/6/21 | 218 | R.No 217 | Electrical timer not working |
| 12/7/21 | Lab room | ROOM NO 308 | In lab 308 steth room fan is not working. |
| 17/7/21 | ECE | Room 265 | Mr. Mahalakshmi FAN Repair |
| 27/7/21 | Library | Library | 6P Tube Lights |
| 07/09/21 | MECH | Room No: 214 | Fan not working properly - (CAM LAB) |
| 1/9/2021 | CSE | Room No 217 | Server Room Airconditioner supply Problem |
| 20/9/2021 | CSE | RNo: 462 | Fans problem ^{urgent ***} newelstel ^{SL} |
| 21/9/21 | PD Dept | 147 | Room TUB Lights not working |
| 6-10-21 | EEE | 133, 135 | reading light not working PL |
| 25/10/21 | EEE | 139 | Electrical machine (s -) (2 Fan not working) (1 Fan slow down) |
| 29-10-21 | CSE | 224 | 1 - Fan, 5 - lights, Table power Problem - switch |
| 29-10-21 | CSE | 216 | 2 - Fans; 2 lights; 8 - Table power switches problem |
| 04/11/2021 | CSE | 208 | 1 - Fan, 2 - lights problem Power computer control No: 9000998749 Labs } contact Name: M. Chaitanya Krishnan |

work completed

work completed

work completed

work completed

work completed

→ M. KOTESWARARAO. work completed

V. Siva Kumar

- P. Srikrishna Rao 1/F July, 2020, Taylor 2 work completed
1000. Glucos 24/7 3. Andhra prd 1/3 P. molten
Stabs 1/9/21 205 capures = 3. } P. molten
R. molten 2/9/21 1/3 R. molten
work completed. P. molten
R. molten

work completed

28/3/22 ITBA. CIVIL. Dab. Room-157. Sunch. Repair. 155, 155. Sunch. Repair 156 class Room Sunch. Repair class. Room Fan. Repair Civil. 16 and 154, 155.

29/3/22 Library Library 2 Tube lights. Digital Library 1 Fan Repair.

4/4/22 218 2 Tube lights are not working in Computer Lab (in Two Sets)

366 2 Tube lights, 1 tube light set
371 Fan, tube light set - 1
353 tube light set - 1
341A tube lights - 2
341 tube light - 1

8/4/22 Simulation Lab 1 Fan Repair.

12/4/22 122 A machine hall
① Fan problems

18/4/22 301, 322 I.T. class Room, Staff Room, Electrical Sockets problems.

28/4/22 216, 224 Light, Mcb, Sockets, table Switch has to be replace

20/4/22 Library 2 Fans. 25/4/22 ITBA Room No: 460 - 2 fan problem 15/4/22 CSE Room No: 210 FAN Problem

Raja. 28/4/22 CSE Room No: 216, 224 light MCB, sockets, tables, switch problem

29/4/22 EEE Room No: 342 8 Fans condensers Problem. Fit to the New condensers in MPC Lab.

10/5 C.E. Room No 151. Civil Library Fan Repair (Brand New)

12/5/22 ECE ① ceiling Fan Change from front to back in class Room No 301A
② ceiling fan (new) Required in class No: 341A
③ New ceiling Fan Required in class No: 365
④ Fan condenser Problem in class No: 365

24/5/22 CSE Dept 3+3 Gang Box, English lab, CSE Dept Purpose Computer for M. Gangas

25/5/22 IT. Dept 301 fan Repair

216, 224, complaint on Written 28/4/22, Same problem not Cleared. (MCB, table switch(224), Gang boxes, switch(216) tube light problem replaced with new bulb

104

105

date Branch Switch Board Repair Sign
 4/7/2022 CIVIL 143-154-155-FAN-Table-Box G.Raja
 4/7/2022 ECE Room No: 266 and 258 Tubelight Repair A. Raju
 17/7/2022 P2 Port Networking FAN 151 ~~3rd floor~~
 Room NO- 148. Room 3rd HAB
 (8/7/2022 MCCB ⁽³⁺³⁾ ~~3rd floor~~ Box Boarding (No: 4) G.Raja
 cables (348)

12/7/2022 FED physics lab. R.No: 424, 422A
 26/7/2022 Tubelight Boarding M. Raju
 12/7/2022 MECH Machine lab R.No: 122 ~~26/7/2022~~ &
 Tubelight Boarding

13/7/22 NBA. Not working FAN. M.B.A 451 A.L.V. Abad

24/7/22 M.B.A 463, 464, 460 Lab 28 - ALVAN
 FAN Repair Not working
 FANS

14/20/22 CSE 2/16 lab light & table M. July
 power plug & MCB problem

2/19/22 CSE 2/16 Lab 2 Tubelight & MCB T. Sanu
 problem

29/9/22 CSE Room No:- 462 English Lab
 Installation of Projector, ^{ceiling} Stand Gangaram

01/10/22 Mech Room No: 123, fan not working new

date Branch work completed Arun, Rajesh
 2 Boxes Replace Arun, Rajesh, MohanRenu
 Replaced ~~Not working~~

work completed Arun, Rajesh.
 1 tubelight problem completed Arun, Rajesh.
 work completed Arun

| Date | Branch | Repair Work. Room | |
|------------|--------|--|------------------------|
| 13/03/2023 | FED | Room No: 422 c ² (EP lab) Fan problem | M. Raju 1515 hours. |
| 14/03/2023 | FED | Room No: 446 (Physics room) (Fan not working) | AC |
| 20/03/2023 | IT | Room No: 309. Fan Repairs | client |
| 29/03/23 | CSE | Room 224 MCB problem | MB |
| 29/03/23 | CSE | Room 216 Lights -4 problem failed | J. S. Jaiswal |
| 29/03/23 | CSE | Room 224 Fan switch. Not working. | DM. July |
| 29/03/23 | EEE | Room No: 251 (staff room) Fan problem | B. B. S. Babu |
| 11/04/23 | CSE | Room No: 201, 224/1a B232, Staff room. Fan not working | D. S. A. S. L. |
| 12/04/23 | FED | Room No: 419 (classroom) Fan not working | |
| 20/04/23 | EEE | Room No. 247 Change the place of socket & switch | MB |
| 20/04/23 | CE | Room No: 153 (TE lab) Tube light or Switch problem (kalyan) | |
| 20/04/23 | MIS | MOS Lab - Tube light (Abdul Kalam Room) | |

| | |
|--|--------------------|
| Work attended Fan Repairs. | Nagendra Rajesh |
| Work attended new fan. | Rajesh |
| | Nagendra |
| MCB problem (changed) | Rajesh & Nagendra |
| New fan & Led & Starter | Rajesh Nagendra |
| Condenser charged | Rajesh & Nagendra |
| 224 lab one new fan & one led replaced | Rajesh & Nagendra |
| Capacitor changed | Rajesh & Nagendra |
| Capacitor | Rajesh & Nagendra |
| Switch & tube light problem (Anne switching 20watt led Replaced. | Rajesh |
| work completed. | Nagendra |

Date: 09/06/22. Mechanical Engg Dept Exocell system Prob. P.G. Ansley → Mech Exam cell desktop formatted and OS, softwares, Printer installed. V.V.Sun..

15/06/22. Room no 320

PC problem

Real time clock power loss Error.

(A)

→ CMOS battery problem changed the CMOS now System OIC.

V.V.Sun..
9/6/22

15/06/22. Room no 320

PC problem

Real time clock power loss Error.

→ CMOS battery problem changed the CMOS now System OIC.

V.V.Sun..
17/6/2022

21/06/2022 Room no : 361 (ECE Dept Library)

PC not getting started.

→ RAM problem cleared. Now System OIC.

V.V.Sun..
22/6/2022

30/06/2022 Room no 320

OS problem

(B)

→ New OS installed on 30/06/2022. Now system working fine.

V.V.Sun..
2/7/2022

30/06/2022 Room No 260

NET problem

P. Jekar

→ problem solved

1/08/2022 ECE Dept office

System is not working

C. Subba Reddy

→ ECE HOD Said system is slow. I Said 2GB RAM and 128 GB SSD HOD wanted.

V.V.Sun..
2/8/2022

2/08/2022 CSE Dept. (Room 218)

OST 06, 18, 27, 30, 34

{ system problem }

{ No display streaks }

→ 6 no's of Systems Cleared.

10/08/2022 ECE Dept office

RAM installed

OS win 8. u/s required

HOD Sir requested

C. Subba Reddy

HOD

→ 2GB RAM & 128 SSD required intimated to HOD ECE Sir.

V.V.Sun..
11/8/2022

10/08/2022 NCC office

Office system is not working

H.M. Dhadhurya Naik

ANO

→ System changed. Now System OIC.

V.V.Sun..
12/8/2022

6/1/22 251 Civil Library
System problem.

→ Problem cleared. power cord problem.
V.V.Sure.

24/01/22 342 MP MC Lab
moodle system switch problem (M)

→ switch ok. System under warranty. V.V.Sure.

4/02/22 447 Staff Room
system problem 8500401246 from
V. Praveen Kumar MBA.

→ Problem solved. Audio drivers problem.
V.V.Sure.

4/2/22 Digital library
systems no 14 and 17 network at Kochi

→ Two systems cleared. now systems ok.
one system OS, one system
CMOS battery.

5/2/22 ① Room: 460
Dept. MBA class Room
internet problem → solved
② 2nd Dept. office
internet problem → solved

Jay
HEAD
Dept. of Computer Science & Engg.
PRASAD V. POTHURI
SIDDHARTHA INSTITUTE OF TECHNOLOGY
KANURU, VIZAYAWADA-520007.

16/2/22. CIVIL CAD LAB.

→ 2 mo's of New Systems was assembled and OS
install now ok.

18/2/22. CIVIL CAD LAB.

→ ② Other 2 Systems new one was assembled
V.V.Sure.

19/2/22. ECE Dept (Dispels)
Rooms: (255). One system
Not working. Problem.

→ Mother board problem. intimated to lab technician.
V.V.Sure.

26/2/22 Time - 10 am.
Digital library system not working. Intimated to J. Kaben

→ Cleared the 2 systems.

V.V.Sure.

3/7/2020. Admin office Accounts system anti virus renewal.

→ Kaspersky Antivirus was expired. New licence key was installed, Scanned the sys.

V.V.Sun.

7/7/2020. Tech HOD System Scanner problem. Can't show Scanner.

→ Tech HOD Scanner Problem with USB cable. Cannon lide 200 scanner new cable was Purchased. Now OK.

V.V.Sun.

15/7/2020. CAD lab sys no: 61 CPU not working. No power.

→ Cad lab sys 61 was M/B Prob. New M/B was installed. Now OK.

V.V.Sun.

18/7/2020. Central, Library & Systems not working.

→ Central lib 1 system was os prob. another was power button problem replaced with old one. Now OK.

V.V.Sun.

24/7/2020. CSE HOD System Internet not working.

→ Lan cable problem, resolved the issue. Now OK.

V.V.Sun.

28/7/2020. ROOM no: 261 One System not working.

→ Ram beeps comes, cleaned the RAM and inserted. OK.

V.V.Sun.

6/8/2020. ID Card Computer Problem.

→ HDD problem, HDD not detected. New HDD installed os, softwares done.

V.V.Sun.

11/8/2020. ROOM no: 456. System 'os' problem (Training & Placement)

→ System formatted and os, softwares installed. Now OK.

V.V.Sun.

Jay

HEAD

ACADEMIC YEAR

20

2019 - 2020.

21

10/7/2019

T&P cell System was not working properly.

→ SMPS problem, Power Supply not come new SMPS installed, OK.

V.V.Sun.

14/7/2019

IT HOD UPS was not working.

→ It had ~~as~~ ups problem with Battery. Replaced the new battery and now UPS OK.

V.V.Sun.

19/7/2019

CC lab System no:40 not working.

→ System no:40 was RAM problem, New RAM installed. OK.

V.V.Sun.

22/7/2019

PL LAB System no:25 keyboard not working.

→ System OK. Keyboard is not working wire problem. Replacing the wire and now Keyboard OK.

V.V.Sun.

27/7/2019

A.O office Ramadevi Madam System shows virus.

→ Used virus pendrive and System works malfunctioning, Anti virus installed and cleaned. Some virus was removed.

V.V.Sun.

12/8/2019

principal System problem.

→ Principal Sir System problem with monitor, no power in the monitor. monitor Power Supply problem. Replacing with new monitor.

V.V.Sun.

Jay
HEAD

Dept. of Computer Science & Engg.

ACADEMIC YEAR

2

2018-19

3

6-7-2018 Room NO: 249, CIVIL
CAD LAB Systems repair

Q

→ 2 Systems found problems.

one is RAM problem, replaced the RAM
Other one is SMPS problem, New SMPS
installed. OK.

V.V.Sen..

10-7-2018 Room 457 (MBA)
System is not working

J21.

→ System Monitor problem, NO power. V.V.Sen..
Monitor replaced with working one.

13/7/2018 Room NO: 153 CIVIL
DEPT TE Lab CPU Not working

→ TE Lab Server had found problem
with noise. Data is taken and
new one installed.

V.V.Sen..

Mechanisms
HEAD
Dept. of Computer Science & Engg.
PRASAD V. POTHURI
SIDDHARTHA INSTITUTE OF TECHNOLOGY
KANURU, VIJAYAWADA-520007.

15/7/2018 Room NO: 342 ECE DEPT
MPPMC lab 2 Systems are
not working

→ one System prob found with power
switch. Second one ~~had~~ OS problem.
cleared the both problems.

V.V.Sen..

18/7/2018 Room NO: 261 Communication
System lab NASR Sir System keyboard
not working

→ System Keyboard is not working.
Broken the wire. New one replaced.

V.V.Sen..

8/8/2018 342 MPC Lab Moodle system
switch Problem.

→ Another old System Switch was taken
and inserted into moodle System.
Now System is OK.

Mechanisms
HEAD
Dept. of Computer Science & Engg.
PRASAD V. POTHURI